


2号機取水路水平坑 側壁写真(基数No.130~133)




側壁(上半)No.130 写真





側壁(上半)No.132 写真




側壁(上半)No.131 写真



側壁(上半)No.133 写真




側壁(下半南側)No.130~131 写真



側壁(下半南側)No.132~133 写真




側壁(下半北側)No.132~133 写真




側壁(下半北側)No.130~131 写真なし


2号機取水路水平坑 側壁写真(基数No.134~137)




側壁(上半)No.134 写真




側壁(上半)No.136 写真



側壁(上半)No.135 写真




側壁(上半)No.137 写真



側壁(下半南側)No.134~135 写真なし



側壁(下半南側)No.136~137 写真




側壁(下半北側)No.136~137 写真




側壁(下半北側)No.134~135 写真


2号機取水路水平坑 側壁写真(基数No.138~141)




側壁(上半)No.138 写真




側壁(上半)No.140 写真



側壁(上半)No.139 写真




側壁(上半)No.141 写真



側壁(下半南側)No.138~141 写真なし




側壁(下半北側)No.140~141 写真




側壁(下半北側)No.138~139 写真

2号機取水路水平坑 側壁写真(基数No.142~145)




側壁(上半)No.142 写真




側壁(上半)No.144 写真



側壁(上半)No.143 写真



側壁(上半)No.145 写真



側壁(下半南側)No.142~143 写真なし



側壁(下半南側)No.144~146 写真




側壁(下半北側)No.144~145 写真




側壁(下半北側)No.142~143 写真


2号機取水路水平坑 側壁写真(基数No.146~149)




側壁(上半)No.146 写真




側壁(上半)No.148 写真



側壁(上半)No.147 写真




側壁(上半)No.149 写真



側壁・天端No.146~149 スケッチ



側壁(下半南側)No.144~146 写真



側壁(下半南側)No.148~150 写真


側壁(下半南側)No.147 写真なし



側壁(下半北側)No.146~148 写真

側壁(下半北側)No.149 写真なし


2号機取水路水平坑 側壁写真(基数No.150~153)




側壁(上半)No.150 写真




側壁(上半)No.152 写真




側壁(上半)No.151 写真



側壁(上半)No.153 写真




側壁・天端No.150~153 スケッチ



側壁(下半南側)No.148~150 写真




側壁(下半南側)No.150~152 写真




側壁(下半南側)No.152~154 写真

- 側壁写真範囲
- 節理
- 安山岩(均質)
- 安山岩(角礫質)
- 凝灰角礫岩



側壁(下半北側)No.152~154 写真



側壁(下半北側)No.150~152 写真