




2号機取水路水平坑 側壁写真(基数No.194~197)




側壁(上半)No.194 写真





側壁(上半)No.196 写真




側壁(上半)No.195 写真



側壁(上半)No.197 写真



側壁(下半南側)No.193~194 写真




側壁(下半南側)No.195~196 写真




側壁(下半南側)No.197~198 写真



側壁(下半北側)No.197~198 写真




側壁(下半北側)No.195~196 写真




側壁(下半北側)No.192~194 写真


2号機取水路水平坑 側壁写真(基数No.198~201)




側壁(上半)No.198 写真




側壁(上半)No.200 写真



側壁(上半)No.199 写真




側壁(上半)No.201 写真



側壁写真範囲
 安山岩(均質)
 節理
 安山岩(角礫質)


側壁・天端No.198~201 スケッチ




側壁(下半南側)No.197~198 写真




側壁(下半南側)No.199~200 写真



側壁(下半南側)No.200~202 写真



側壁(下半北側)No.201~202 写真




側壁(下半北側)No.199~200 写真




側壁(下半北側)No.197~198 写真


2号機取水路水平坑 側壁写真(基数No.202~205)




側壁(上半)No.202 写真




側壁(上半)No.204 写真




側壁(上半)No.203 写真




側壁(上半)No.205 写真




側壁(下半南側)No.201~202 写真




側壁(下半南側)No.203 写真なし



側壁(下半南側)No.204~205 写真




側壁(下半北側)No.203~206 写真




側壁(下半北側)No.201~202 写真


2号機取水路水平坑 側壁写真(基数No.206~209)




側壁(上半)No.206 写真




側壁(上半)No.208 写真




側壁(上半)No.207 写真




側壁(上半)No.209 写真




側壁(下半南側)No.206~207 写真




側壁(下半南側)No.208~210 写真



側壁(下半北側)No.208~209 写真




側壁(下半北側)No.206~207 写真




側壁(下半北側)No.203~206 写真


2号機取水路水平坑 側壁写真(基数No.210~213)




側壁(上半)No.210 写真





側壁(上半)No.212 写真




側壁(上半)No.211 写真




側壁(上半)No.213 写真




側壁(下半南側)No.208~210 写真



側壁(下半南側)No.211~213 写真



側壁(下半北側)No.213~215 写真




側壁(下半北側)No.210~212 写真

2号機取水路水平坑 側壁写真(基数No.214~217)




側壁(上半)No.214 写真



側壁(上半)No.216 写真



側壁(上半)No.215 写真




側壁(上半)No.217 写真




側壁(下半南側)No.214~215 写真



側壁(下半南側)No.216~217 写真




側壁(下半北側)No.216~217 写真




側壁(下半北側)No.213~215 写真


2号機取水路水平坑 側壁写真(基数No.218~221)




側壁(上半)No.218 写真





側壁(上半)No.220 写真




側壁(上半)No.219 写真




側壁(上半)No.221 写真



側壁(下半南側)No.218~219 写真



側壁(下半南側)No.220~221 写真




側壁(下半北側)No.220~221 写真




側壁(下半北側)No.218~219 写真


2号機取水路水平坑 側壁写真(基数No.222~225)




側壁(上半)No.222 写真





側壁(上半)No.224 写真



側壁(上半)No.223 写真




側壁(上半)No.225 写真




側壁(下半南側)No.222~223 写真



側壁(下半南側)No.224~225 写真




側壁(下半北側)No.224~225 写真




側壁(下半北側)No.222~223 写真


2号機取水路水平坑 側壁写真(基数No.226~229)




側壁(上半)No.226 写真





側壁(上半)No.228 写真




側壁(上半)No.227 写真




側壁(上半)No.229 写真




側壁(下半南側)No.226~227 写真



側壁(下半南側)No.228~229 写真




側壁(下半北側)No.228~229 写真




側壁(下半北側)No.226~227 写真


2号機取水路水平坑 側壁写真(基数No.230~233)




側壁(上半)No.230 写真





側壁(上半)No.232 写真




側壁(上半)No.231 写真




側壁(上半)No.233 写真




側壁(下半南側)No.230~231 写真



側壁(下半南側)No.232~233 写真




側壁(下半北側)No.232~233 写真




側壁(下半北側)No.230~231 写真


2号機取水路水平坑 側壁写真(基数No.234~237)




側壁(上半)No.234 写真





側壁(上半)No.236 写真




側壁(上半)No.235 写真




側壁(上半)No.237 写真




側壁(下半南側)No.234~235 写真



側壁(下半南側)No.236~238 写真




側壁(下半北側)No.236~237 写真




側壁(下半北側)No.234~235 写真


2号機取水路水平坑 側壁写真(基数No.238~241)




側壁(上半)No.238 写真




側壁(上半)No.240 写真




側壁(上半)No.239 写真




側壁(上半)No.241 写真




側壁・天端No.238~241 スケッチ





側壁(下半南側)No.236~238 写真




側壁(下半南側)No.239~240 写真



側壁(下半南側)No.241~242 写真




側壁(下半北側)No.242~241 写真




側壁(下半北側)No.238~240 写真


2号機取水路水平坑 側壁写真(基数No.242~245)




側壁(上半)No.242 写真





側壁(上半)No.244 写真



側壁(上半)No.243 写真



側壁(上半)No.245 写真




側壁・天端No.242~245 スケッチ



側壁(下半南側)No.241~242 写真



側壁(下半南側)No.243~244 写真



側壁(下半南側)No.245~247 写真



側壁(下半北側)No.245~246 写真




側壁(下半北側)No.243~244 写真




側壁(下半北側)No.241~242 写真


2号機取水路水平坑 側壁写真(基数No.246~249)




側壁(上半)No.246 写真





側壁(上半)No.248 写真




側壁(上半)No.247 写真




側壁(上半)No.249 写真




側壁(下半南側)No.245~247 写真




側壁(下半南側)No.247~248 写真




側壁(下半南側)No.249~251 写真



側壁(下半北側)No.249~250 写真




側壁(下半北側)No.247~249 写真




側壁(下半北側)No.245~246 写真

2号機取水路水平坑 側壁写真(基数No.250~253)




側壁(上半)No.250 写真




側壁(上半)No.252 写真



側壁(上半)No.251 写真



側壁(上半)No.253 写真



側壁(下半南側)No.249~251 写真



側壁(下半南側)No.252~254 写真



側壁(下半北側)No.251~253 写真



側壁(下半北側)No.249~250 写真